

Inspection Photos

Loc#425510


Operator: Laramie

Inspection Number: 680102921

Inspection Date: 4/16/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

2013 aerial view of AL Well API# 077- 08633.

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#425510



Photo#2:
2015 aerial view of AL Well API# 077- 08633 and Laramie Loc#425510

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#425510



Photo#3:


2017 aerial view of AL Well API# 077- 08633 and Laramie Loc#425510

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#425510



Photo#4:

Image of plans for construction & disturbance areas for Water Impoundment facility. Red **X** indicates AL Well position.

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#425510



Photo#5:

View of Location April 16, 2018. Last year's desiccated thistle plants in foreground.

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#425510



Photo#6:
Areas of site are bare of vegetation or are infested with weedy species.



Photo#7:

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#425510



Photo#8:
Thistle rosettes are emerging on site.

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#425510