

Inspection Photos
Location Name: McCallum Unit 9
API: 05-057-05115



Photo 1. Overview of location taken at entrance facing north.



Photo 2. Stained soil at wellhead.