

Inspection Photos
Location Name: Hough#1-12
Location ID: 319713



Photo#1 Production Tanks



Photo#2 Vertical Heater Treater

Inspection Photos
Location Name: Hough#1-12
Location ID: 319713



Photo#3 Produced water tanks



Photo#4 Burner stack missing sight glass or plug

Inspection Photos
Location Name: Hough#1-12
Location ID: 319713



Photo#5 Propane Tank



Photo#6 Pumpjack/Wellhead

Inspection Photos
Location Name: Hough#1-12
Location ID: 319713



Photo#7 Unused equipment



Photo#8 Unused equipment

Inspection Photos
Location Name: Hough#1-12
Location ID: 319713



Photo#9 Chemical pump and tank