

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401557748

Receive Date:

07/06/2018

Report taken by:

PETER GINTAUTAS

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80217-3779</u>
Contact Person: <u>Phil Hamlin</u>	Email: <u>Phil.Hamlin@anadarko.com</u>	Mobile: <u>()</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 5140 Initial Form 27 Document #: 2608077

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input checked="" type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>LOCATION</u>	Facility ID: <u>328928</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>HSR-MOORHEAD-63N66W 5SWSW</u>		Latitude: <u>40.247878</u>	Longitude: <u>-104.808553</u>
		** correct Lat/Long if needed: Latitude: <u>40.246836</u>	Longitude: <u>-104.806753</u>
QtrQtr: <u>SWSW</u>	Sec: <u>5</u>	Twp: <u>3N</u>	Range: <u>66W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Commercial – Sod Farm

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

Water well and occupied building approximately 420 feet (ft) west, surface water approximately 650 ft east, and groundwater approximately 2 ft below ground surface (bgs).

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☒ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	See attached data	Groundwater Sampling/Laboratory Analysis
Yes	SOILS	50' N-S X 60' E-W X 5' bgs (max)	Soil Sampling/Laboratory Analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

In January 2010, soil with historical petroleum hydrocarbon impacts was encountered near the HSR-Chaknova 14-5, HSR-Moorhead 13-5, HSR-Bell 12-5, HSR-Creaseon 11-5 production tank while digging a trench for the emission control device (ECD) lines. The volume of the release is unknown. The petroleum hydrocarbon impacted soil was excavated.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Please refer to the Form 27 submitted to the Colorado Oil and Gas Conservation Commission (COGCC) on July 27, 2010.

Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater monitoring has been performed on a quarterly basis since June 2010.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 12

Number of soil samples exceeding 910-1 2

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 3000

Groundwater

Number of groundwater samples collected 418

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) 2'

Number of groundwater monitoring wells installed 18

Number of groundwater samples exceeding 910-1 103

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

NA / ND

-- Highest concentration of TPH (mg/kg) 4240

NA Highest concentration of SAR

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 4

-- Highest concentration of Benzene (µg/l) 4500

-- Highest concentration of Toluene (µg/l) 32

-- Highest concentration of Ethylbenzene (µg/l) 1200

-- Highest concentration of Xylene (µg/l) 7900

NA Highest concentration of Methane (mg/l)

OTHER INVESTIGATION INFORMATION

☒ Were impacts to adjacent property or offsite impacts identified?

Groundwater impacts were detected in the adjoining field north of the tank battery.

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Please refer to the Form 27 submitted to the COGCC on July 27, 2010.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Please refer to the Form 27 submitted to the COGCC on July 27, 2010.

Due to persistent, elevated BTEX concentrations in multiple site monitoring wells, an air sparging (AS) and soil vapor extraction (SVE) system was installed at the site to remediate the dissolved-phase petroleum hydrocarbon plume. The AS/SVE system was designed to introduce ambient air into the subsurface water column to promote volatilization and aerobic microbial decomposition of dissolved-phase petroleum hydrocarbons. Installation and operation of the full-scale AS/SVE system occurred in February 2016. Kerr-McGee submitted a UIC Permit Application to Region 8 of the USEPA which was subsequently approved on March 17, 2015. A copy of the February 2015 UIC Permit Application and the March 2015 Rule Authorization: Aquifer Remediation Well approval letter from Region 8 are attached.

The AS/SVE system started up in February 2016. The system is comprised of eight wells connected by a combination of surface and subsurface high-density polyethylene piping to a remediation trailer powered by electricity. Two AS wells were added in March 2018 to increase system influence around the separators. The remediation system included valves at all the AS wellheads to allow for uninterrupted flow control, measurement, and adjustment. AS was accomplished using a 10-horsepower-driven Rietschle Thomas DLR 150 rotary-claw compressor, and SVE was accomplished using a Roots 47 U-RAI DSL rotary-lobe blower housed within the remediation trailer. A diesel-powered tow-behind air compressor was used periodically to increase AS system influence and will be utilized if future remediation operation is necessary. The as-built layout of the full-scale AS/SVE system is depicted on the Site Map attached as Figure 1. Boring logs for the AS wells are attached.

Soil Remediation Summary

☐ In Situ

☐ Bioremediation (or enhanced bioremediation)
☐ Chemical oxidation
☐ Air sparge / Soil vapor extraction
☐ Natural Attenuation
☐ Other

☒ Ex Situ

Yes Excavate and offsite disposal
If Yes: Estimated Volume (Cubic Yards) 500
Name of Licensed Disposal Facility or COGCC Facility ID # 149007
No Excavate and onsite remediation
Land Treatment
Bioremediation (or enhanced bioremediation)
Chemical oxidation
Other

Groundwater Remediation Summary

Yes Bioremediation (or enhanced bioremediation)
No Chemical oxidation
Yes Air sparge / Soil vapor extraction
Yes Natural Attenuation
Yes Other MicroBlaze® Application

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Since the submittal of the Form 27 on July 27, 2010, thirteen additional monitoring wells (MW05 through MW17) and one replacement monitoring well (MW12R) were installed at the site. Field boring logs with well completion diagrams are attached. The monitoring well locations are depicted on Figure 1.

Groundwater monitoring wells MW01 through MW17 are sampled on a quarterly basis for benzene, toluene, ethylbenzene, and total xylenes (BTEX) by United States Environmental Protection Agency (USEPA) Method 8260C. The Groundwater Elevation Contour Map generated using the March 2018 survey data is provided as Figure 2. The groundwater analytical results are summarized in Table 1, and the laboratory analytical report for the March 2018 groundwater monitoring event is attached.

Groundwater monitoring will continue on a quarterly basis until a No Further Action status request is warranted.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☒ Annually ☐ Other _____

Report Type: ☒ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report
☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

The petroleum hydrocarbon impacted soil was transported to the Kerr-McGee Land Treatment Facility in Weld County, Colorado, for recycling.

Volume of E&P Waste (solid) in cubic yards _____ 500

E&P waste (solid) description _____ Petroleum hydrocarbon impacted soil

COGCC Disposal Facility ID #, if applicable: _____ 149007

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____ 0

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

Do all soils meet Table 910-1 standards? Yes _____

Does the previous reply indicate consideration of background concentrations? No _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? No _____

Is additional groundwater monitoring to be conducted? Yes _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site was restored to its pre-release grade. The Kerr-McGee production facility remains at the site.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. 01/22/2010

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/22/2010

Date of commencement of Site Investigation. 02/04/2010

Date of completion of Site Investigation. 12/02/2014

REMEDIAL ACTION DATES

Date of commencement of Remediation. 02/04/2010

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Phil Hamlin

Title: Senior HSE Representative

Submit Date: 07/06/2018

Email: Phil.Hamlin@anadarko.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: PETER GINTAUTAS

Date: 07/09/2018

Remediation Project Number: 5140

COA Type

Description

	Submit reports of site investigation and progress of remediation including results of sampling and analysis on an annual basis or more often until remediation is closed.
--	---

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

<u>Att Doc Num</u>	<u>Name</u>
401557748	FORM 27-SUPPLEMENTAL-SUBMITTED
401574353	LOGS
401629766	SITE MAP
401629767	GROUND WATER ELEVATION MAP
401629836	ANALYTICAL RESULTS
401695030	CORRESPONDENCE
401695031	CORRESPONDENCE

Total Attach: 7 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)