



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jul 3, 2018 1:09:27 PM MDT
Server Receive Date:	Jul 3, 2018 1:09:38 PM MDT
Reference Number:	20180703-1882189144
Location:	101 S Skylane Dr, Durango, CO 81303, USA Jul 3, 2018 1:09:13 PM MDT [ <a href="#">View Map</a> ]

## Information

Name	reclamationtablet
Date	Jul 2, 2018
Well Name	COWEN, GRACE GAS UNIT A 1
API Number	50670741800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other Clean Up Land Owner Debris Grading of Road Grading of Well Pad

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



