

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jul 5, 2018 12:21:11 PM MDT
Server Receive Date:	Jul 5, 2018 12:21:16 PM MDT
Reference Number:	20180705-1882335373
Location:	3089 Co Rd 222, Durango, CO 81303, USA Jul 5, 2018 12:21:11 PM MDT [View Map]

Information

Name	reclamationtablet
Date	Jul 5, 2018
Select State	Colorado Hanstedt 07U-01 1
Action Complete	Hanstedt 07U-01 3 Clean up Operator Debris Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

cut down thistles on site and removed marked anchors **Correction to statement due to typo: Cut down thistles on site and removed. Marked Rig Anchors.**