



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jul 5, 2018 1:04:07 PM MDT
Server Receive Date:	Jul 5, 2018 1:04:16 PM MDT
Reference Number:	20180705-1882339068
Location:	Unknown Location

Information

Name	celkins@gobrainstorm.net
Date	May 29, 2018
Well Name	KLUSMAN GAS UNIT 33-34 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Land Owner Debris Clean Up Weed Debris Clean Up Contaminated Soils Replaced/Repaired Tank Signs

Picture North to South



Picture South to North



Picture East to West



Picture West to East

