

Final Reclamation and Stormwater Inspection

June 28, 2018

Operator: PIONEER NATURAL RESOURCES USA INC – 10084

Location ID: 383611

Inspection Document #: 674902264

Huerfano County, CO

NWSW Section 30 T29S R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S66W30

Location ID: 383611



Photo 1. Photo taken from the access road looking towards the location, facing West. Appears the Operator has performed final reclamation activities on the well location and access road.



Photo 2. Photo taken from the well location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S66W30

Location ID: 383611



Photo 3. Photo taken from the well location, facing East. See comments from Photo 1.



Photo 4. Photo taken from the well location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S66W30

Location ID: 383611



Photo 5. Photo taken from the well location, facing West. See comments from Photo 1.



Photo 6. Photo taken from the South end of the location. Note the gravel that was not removed.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S66W30

Location ID: 383611



Photo 7. Photo taken from the access road, facing North. Note the culvert that is still on location.



Photo 8. Photo taken from the East end of the location.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S66W30

Location ID: 383611



Photo 9. Photo taken from the Reference Area, facing North.



Photo 10. Photo taken from the Reference Area, facing East.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S66W30

Location ID: 383611



Photo 11. Photo taken from the Reference Area, facing South.



Photo 12. Photo taken from the Reference Area, facing West.