

# Final Reclamation and Stormwater Inspection

June 28, 2018

Operator: PIONEER NATURAL RESOURCES USA INC – 10084

Location ID: 324562

Inspection Document #: 674902265

Huerfano County, CO

NWSE Section 25 T29S R67W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 324562



**Photo 1.** Photo taken from the access road looking towards the location, facing Southwest. Appears the Operator has performed final reclamation activities on the well location and access road.



**Photo 2.** Photo taken from the well location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 324562



**Photo 3.** Photo taken from the well location, facing East. See comments from Photo 1.



**Photo 4.** Photo taken from the well location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 324562



**Photo 5.** Photo taken from the well location, facing West. See comments from Photo 1.



**Photo 6.** Photo taken from the location. A List B Colorado Noxious weed species, Scotch thistle (*Onopordum acanthium*), is found at low densities throughout the site .

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 324562



**Photo 7.** Photo taken from the Reference Area, facing North.



**Photo 8.** Photo taken from the Reference Area, facing East.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 324562



**Photo 9.** Photo taken from the Reference Area, facing South.



**Photo 10.** Photo taken from the Reference Area, facing West.