

Inspection Photos

Location Name: Springdale Partners LLC, Springdale Storage 5

API: 05-075-08176



1. Lease sign



2. Wellhead equipment

Inspection Photos

Location Name: Springdale Partners LLC, Springdale Storage 5

API: 05-075-08176



3. Horizontal heater treater & Free water knockout



4. Steel ring containment