

Inspection Photos

Location Name: Springdale Partners LLC, Springdale Storage 2

API: 05-075-05861



1. Lease sign

2. Wellhead equipment



Inspection Photos

Location Name: Springdale Partners LLC, Springdale Storage 2

API: 05-075-05861



3. Horizontal heater treater & Free water knockout



4. Tank Battery



Inspection Photos

Location Name: Springdale Partners LLC, Springdale Storage 2

API: 05-075-05861



5. 6 flowline risers unmarked or locked out

