

Inspection Photo
Quarter Circle 43-33H
API # 045-06782
Inspection # 689301493



Location Photo #1



**Location Photo #2, Unused pipe on West end
of location**

Inspection Photo
Quarter Circle 43-33H
API # 045-06782
Inspection # 689301493



Location Photo #3, unused equipment on west end of location.



Location Photo #4, Housekeeping issue, Weeds.

Inspection Photo
Quarter Circle 43-33H
API # 045-06782
Inspection # 689301493



**Location Photo #5, Housekeeping issue,
Weeds**



**Location Photo #6, Housekeeping issue,
Weeds.**

Inspection Photo
Quarter Circle 43-33H
API # 045-06782
Inspection # 689301493



Location Photo #7, weeds near tank battery



Location Photo #8, Weeds along access road