

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/05/2018

Submitted Date:

07/09/2018

Document Number:

680303469**FIELD INSPECTION FORM**Loc ID 336717 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Findings:**8 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	970-332-3585	gjones@augustusenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278475	WELL	PR	06/23/2005	GW	125-09327	LUEKING 11-19 5N46W	PR

General Comment:Routine Site Inspection - FIR - SATISFACTORY

Location

Lease Road:			
Type	Access		
comment:	Two track - dryland cropland		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electrical motor		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 278475 Type: WELL API Number: 125-09327 Status: PR Insp. Status: PR

Producing Well

Comment: [GW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: Located within dryland cropland with rotational tillage

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT