



## Form Information

|                      |  |
|----------------------|--|
| Form Name:           | <b>Compliance Follow Up Form</b>   |
| Submitter Name:      | Reclamation Tablet (reclamationtablet)   |
| Submission Date:     | Jul 5, 2018 1:25:01 PM MDT   |
| Server Receive Date: | Jul 5, 2018 1:25:14 PM MDT   |
| Reference Number:    | 20180705-1882338990  |
| Location:            | 459 Co Rd 308, Durango, CO 81303, USA<br>Jul 5, 2018 1:24:55 PM MDT [ <a href="#">View Map</a> ] |

## Information

|                       |   |
|-----------------------|---|
| Name                  | reclamationtablet                                   |
| Date                  | Jul 5, 2018   |
| Location Name (Other) | fassett24 01 2                                      |
| Location API (Other)  | 0506708424  |
| Select State          | Colorado  |
| Action Complete       | Clean Up Weed Debris<br>Clean Up Contaminated Soils |

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Completed work description



cut down thistles on site and removed mowed  
around equipment cleaned up contaminated soils