

Inspection Photos

Location Name: Horseshoe Canyon 3-28 and Spill/Release ID #455436

API: 05-077-08656

Inspection Date: July 3, 2018



Photo #1 – Uncontrolled weeds at wellhead.



Photo #2 – Localized accumulation of oil-stained soil at wellhead.



Inspection Photos

Location Name: Horseshoe Canyon 3-28 and Spill/Release ID #455436

API: 05-077-08656

Inspection Date: July 3, 2018



Photo #3 – Uncontrolled weeds overgrowing open-top produced water tank and encroaching on heated horizontal separator.



Photo #4 – Operator was notified of an audible leak detected at heated horizontal separator on inspection date.



Inspection Photos

Location Name: Horseshoe Canyon 3-28 and Spill/Release ID #455436

API: 05-077-08656

Inspection Date: July 3, 2018



Photo #5 – View to northeast of backfilled flowline excavation area inside of BLM Right of Way.



Photo #6 – View to northwest of backfilled excavation inside of intermittent stream.