

Inspection Photos
Location Name: BALLANTINE 4-30 A BATTERY
Facility ID: 262596



Photo 1. Tank battery



Photo 2. Erosion south side of battery

Inspection Photos
Location Name: BALLANTINE 4-30 A BATTERY
Facility ID: 262596



Photo 3. Erosion under tank battery containment



Photo 4. Erosion undermining emission control device platform

Inspection Photos
Location Name: BALLANTINE 4-30 A BATTERY
Facility ID: 262596



Photo 5. Erosion under tank battery containment



Photo 4. Erosion on entrance to tank battery