


PUCKETT 14-6D
Api# 05-045-07670
Inspection # 689701596



Location photo



PUCKETT 14-6D
Api# 05-045-07670
Inspection # 689701596



NFPA sticker needs replaced.

PUCKETT 14-6D
Api# 05-045-07670
Inspection # 689701596



Tank missing information. Operator contact info and volume not on tank.



Tank missing information. Operator contact info and volume not on tank.

PUCKETT 14-6D
Api# 05-045-07670
Inspection # 689701596



Tank missing information. Operator contact info and volume not on tank.



Tank missing information. Operator contact info and volume not on tank.