

Inspection Photos  
Location Name: NVega 3A Pad  
Location ID: 334487



**Photo 1. Missing LOTO tags.**



**Photo 2. Location.**