

# Final Reclamation Inspection

July 3, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-12851

Inspection Document #: 682403759

Weld County, CO

SWNW Section 25 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: ANDERSON-COOMBS #5  
API: 05-123-12851



**Photo 1.** Photo taken from the entrance of the well location, facing North. Well location has not meet Rule 1004 standards, as bare patches and weedy, annuals (Kochia) were observed. Also, appears some gravel remains along portions of the access road. All equipment has been removed from the well location. The offsite tank battery has not meet Rule 1004 standards, as bare patches and weedy, annuals (Kochia) were observed.- see photos 3-4.



**Photo 2.** Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: ANDERSON-COOMBS #5  
API: 05-123-12851



**Photo 3.** Photo taken from the offsite tank battery location (40.366600,-104.732970), facing East. See comments under Photo 1.



**Photo 4.** Photo taken from the offsite tank battery location, facing West. See comments under Photo 1.