

Final Reclamation Inspection

July 3, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-11649

Inspection Document #: 682403763

Weld County, CO

NESW Section 25 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON-COOMBS #1
API: 05-123-11649



Photo 1. Photo taken from the well location, facing North. Appears the well location has been converted to a dog park. The offsite tank battery has not meet Rule 1004 standards, as bare patches and weedy, annuals (Kochia) were observed.- see photos 5-6.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: ANDERSON-COOMBS #1
API: 05-123-11649



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: ANDERSON-COOMBS #1
API: 05-123-11649



Photo 5. Photo taken from the offsite tank battery location (40.366600,-104.72797), facing West. See comments under Photo 1.



Photo 6. Photo taken from the offsite tank battery location, facing East. See comments under Photo 1.