

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2018

Submitted Date:

07/11/2018

Document Number:

677900757

FIELD INSPECTION FORM

Loc ID 303091 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252442	WELL	PR	09/13/2007	GW	125-06316	MILL IRON 1-11	PR

General Comment:

[Routine Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by vault		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign by compressor		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Metal panels around meter shed		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around compressor, sump and chemical tank		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead, VGS and meter run		
Corrective Action:		Date:	
Equipment:			
Type: Vertical Separator	# 3		corrective date
Comment:	1-Vertical gas separator 50% buried by meter run for Mill Iron well 1-Vertical gas separator 50% buried by meter shed used by Bitter Creek 1-Vertical gas separator 50% buried on north side of compressor for field gas		

Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Skid mounted field gas powered compressor. Schramm Compressor		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	2-Foundation GMR 1-Bitter Creek GMR		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Mark all deadmen		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Electric panel, 2-telemetry equipment, lube oil tank w/containment		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
USED OIL	1	<50 BBLs	CONCRETE SUMP/VAULT		40.073640,-102.488710
Comment:	Sump buried on north side of compressor				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	1500gal
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 252442 Type: WELL API Number: 125-06316 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT