

# Final Reclamation Inspection

July 3, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-15605

Inspection Document #: 682403771

Weld County, CO

SESW Section 23 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources



**Photo 1.** Photo taken from the central tank battery, facing West. Germination was observed at the location but large patches of bare ground with weedy, annual vegetation was observed. At a minimum, the Operator needs to control the weedy, annual vegetation (Kochia) per Rule 603.f. Operator may need to perform additional reclamation activities, as large bare patches were observed.



Inspection Photos  
Location Name: WIEDEMAN #J23-14  
API: 05-123-15605



**Photo 2.** Photo taken from the central tank battery, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: WIEDEMAN #J23-14  
API: 05-123-15605



**Photo 3.** Photo taken from the central tank battery, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: WIEDEMAN #J23-14  
API: 05-123-15605



**Photo 4.** Photo taken from the well location, facing South. Well location appears reflective of reference areas.



**Photo 5.** Reference photo taken east of the well location, facing East. Well location appears reflective of reference areas.