

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401701934

Date Received:

07/12/2018

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 5 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Tesla Dougherty

Phone

970-304-5204

Email

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 684905508

Inspection Date: 06/12/2018

FIR Submit Date: 06/12/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 331106

Location Name: LILLI FIELD UNIT-68N58W Number: 7NENW County: WELD

Qtrqr: NENW Sec: 7 Twp: 8N Range: 58W Meridian: 6

Latitude: 40.681700 Longitude: -103.907710

FACILITY - API Number: 05-123- -00 Facility ID: 258556

Facility Name: LILLI FIELD UNIT Number: 3-7

Qtrqr: NENW Sec: 7 Twp: 8N Range: 58W Meridian: 6

Latitude: 40.681700 Longitude: -103.907710

CORRECTIVE ACTIONS:

**1** CA# 116747

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 07/12/2018

Response: CA COMPLETED

Date of Completion: 06/28/2018

Operator  
Comment:

The berm has been repaired.

COGCC Decision: \_\_\_\_\_

Date: 7/12/2018 5:39:35 PM

## Page 2 of 2