

Well Name: V D Helton 1 and Helton 1A **API #** 05-067-05749 05-067-08175
Inspection Number: 680602766
Corrective Action: Musk thistle observed within the project area.
Correction Action Due: 7/13/2018
Action Completed: 7/9/2018
Action Taken: Treat noxious weeds within project area, continue to monitor and re-treat as necessary.

