

Well Name: Julian Gas Unit # 2 **API #** 05-067-07931
Inspection Number: 680602772
Corrective Action: Unmarked rig anchor on western portion of location.
Correction Action Due: 7/29/2018
Action Completed: 7/3/2018
Action Taken: Removed rig anchor



