

Inspection Photos

07/11/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 331849

Inspection Doc. Number: 682503566
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 331849



Photo 1: Photo taken from the location, facing north. Previous inspection required reclamation activities to be conducted on location and access road. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence of reclamation.



Photo 2: Photo taken from the location, facing west. Previous inspection required reclamation activities to be conducted on location and access road. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence of reclamation.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 331849



Photo 3: Photo taken from the south end of the location. Previous inspection required management and removal of noxious weeds.

Photo shows Diffuse Knapweed (lighter, grey-green plants, white colored flowers) remains prevalent on location and have not been managed/removed. Plants are flowering or have matured and are preparing to seed.



Photo 4: Photo taken from the south end of the location. Previous inspection required management and removal of noxious weeds.

Photo shows Diffuse Knapweed (lighter, grey-green plants, white colored flowers) remains prevalent on location and have not been managed/removed. Plants are flowering or have matured and are preparing to seed.