

Inspection Photos

07/11/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 455471

Inspection Doc. Number: 682503580
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northern interim areas of the location, facing north. Previous inspection required management and removal of noxious weeds.

Photo shows Diffuse Knapweed (lighter, grey-green plants, white colored flowers) remains prevalent on location and access roads. Though there is evidence of herbicide, spraying does not appear to have been sufficient as many plants appear to be viable and have continued to mature/flower



Photo 2: See comments under photo 1.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 455471



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1