

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Albert Martinez #1 pump jack and well head.



Well head is wet and surrounding soil is stained with oil.

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Gas bubbling out of oil on well head.



Tank battery for Albert Martinez #1 and Nielson #4 (right).