

Inspection Photos
Location Name: Bulldog 5-31H-790
API: 05-081-07727



Photo 1. Overview of location taken at entrance facing south.

Inspection Photos
Location Name: Bulldog 5-31H-790
API: 05-081-07727



Photo 2. Pit.



Photo 3. Unmarked risers.

Inspection Photos
Location Name: Bulldog 5-31H-790
API: 05-081-07727



Photo 4. Unmarked risers.



Photo 5. Unmarked riser.