

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/06/2018

Submitted Date:

07/08/2018

Document Number:

689701582**FIELD INSPECTION FORM**

Loc ID 323841	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 5 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>			

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210786	WELL	PR	09/15/1987	GW	045-06544	FORSHEE W-28-2	PR
210945	WELL	PR	08/02/2001	GW	045-06703	FORSHEE GV 86-2	PR
294424	WELL	PR	04/16/2011	GW	045-15415	CHARIS PA 314-2	PR
294425	WELL	PR	04/16/2011	GW	045-15414	CHARIS PA 413-2	PR
294426	WELL	PR	04/16/2011	GW	045-15413	CHARIS PA 324-2	PR
433892	WELL	PR	08/16/2014	GW	045-22133	WPX ENERGY PA 43-3	PR
433893	WELL	PR	05/31/2014	GW	045-22134	WPX ENERGY PA 23-2	PR
433894	WELL	PR	06/09/2014	GW	045-22135	WPX ENERGY PA 544-3	PR
433895	WELL	PR	05/31/2014	GW	045-22136	WPX ENERGY PA 522-2	PR
433896	WELL	PR	06/29/2014	GW	045-22137	WPX ENERGY PA 14-2	PR
433897	WELL	PR	03/01/2015	GW	045-22138	WPX ENERGY PA 513-2	PR
433898	WELL	PR	06/21/2014	GW	045-22139	WPX ENERGY PA 514-2	PR
433899	WELL	PR	09/02/2014	GW	045-22140	WPX ENERGY PA 344-3	PR
433900	WELL	PR	05/31/2014	GW	045-22141	WPX ENERGY PA 512-2	PR
433902	WELL	PR	06/10/2014	GW	045-22142	WPX ENERGY PA 313-2	PR
433904	WELL	PR	09/02/2014	GW	045-22143	WPX ENERGY PA 44-3	PR
433906	WELL	PR	06/29/2014	GW	045-22144	WPX ENERGY PA 414-2	PR
433907	WELL	PR	09/02/2014	GW	045-22145	WPX ENERGY PA 343-3	PR
433908	WELL	PR	06/21/2014	GW	045-22146	WPX ENERGY PA 424-2	PR
433909	WELL	PR	06/10/2014	GW	045-22147	WPX ENERGY PA 323-2	PR
433910	WELL	PR	06/29/2014	GW	045-22148	WPX ENERGY PA 24-2	PR
433911	WELL	PR	06/21/2014	GW	045-22149	WPX ENERGY PA 524-2	PR
433912	WELL	PR	08/16/2014	GW	045-22150	WPX ENERGY PA 443-3	PR
433913	WELL	PR	06/07/2014	GW	045-22151	WPX ENERGY PA 444-3	PR

433914	WELL	PR	05/31/2014	GW	045-22152	WPX ENERGY PA 13-2	PR
--------	------	----	------------	----	-----------	--------------------	----

General Comment:
[Follow up inspection to 5/2/2018 inspection 689701317. Weeds have not been controled.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Volumes on tank labels have been repaired.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	C.A. from previous inspection 7/6/2018 Doc [#689701317] Weeds and dead weed debris near wells and equipment. Corrective action not completed. More weeds are coming up on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/14/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Fencing around wells is in disrepair.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: <u>210786</u>	Type: <u>WELL</u>	API Number: <u>045-06544</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>210945</u>	Type: <u>WELL</u>	API Number: <u>045-06703</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>294424</u>	Type: <u>WELL</u>	API Number: <u>045-15415</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>294425</u>	Type: <u>WELL</u>	API Number: <u>045-15414</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>294426</u>	Type: <u>WELL</u>	API Number: <u>045-15413</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433892</u>	Type: <u>WELL</u>	API Number: <u>045-22133</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433893</u>	Type: <u>WELL</u>	API Number: <u>045-22134</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433894</u>	Type: <u>WELL</u>	API Number: <u>045-22135</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433895</u>	Type: <u>WELL</u>	API Number: <u>045-22136</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433896</u>	Type: <u>WELL</u>	API Number: <u>045-22137</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433897</u>	Type: <u>WELL</u>	API Number: <u>045-22138</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433898</u>	Type: <u>WELL</u>	API Number: <u>045-22139</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433899</u>	Type: <u>WELL</u>	API Number: <u>045-22140</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433900</u>	Type: <u>WELL</u>	API Number: <u>045-22141</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433902</u>	Type: <u>WELL</u>	API Number: <u>045-22142</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433904</u>	Type: <u>WELL</u>	API Number: <u>045-22143</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433906</u>	Type: <u>WELL</u>	API Number: <u>045-22144</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433907</u>	Type: <u>WELL</u>	API Number: <u>045-22145</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433908</u>	Type: <u>WELL</u>	API Number: <u>045-22146</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Inspector Name: LONGWORTH, MIKE

Facility ID: 433909	Type: WELL	API Number: 045-22147	Status: PR	Insp. Status: PR
Facility ID: 433910	Type: WELL	API Number: 045-22148	Status: PR	Insp. Status: PR
Facility ID: 433911	Type: WELL	API Number: 045-22149	Status: PR	Insp. Status: PR
Facility ID: 433912	Type: WELL	API Number: 045-22150	Status: PR	Insp. Status: PR
Facility ID: 433913	Type: WELL	API Number: 045-22151	Status: PR	Insp. Status: PR
Facility ID: 433914	Type: WELL	API Number: 045-22152	Status: PR	Insp. Status: PR

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401695889	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516502
689701583	Inspection 689701582 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516500