



**Inspected Facilities**

Facility ID: 449626 Type: WELL API Number: 123-44420 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Patterson 901 Pusher/Rig Manager: Larry Siegel  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300382	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4524820">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4524820</a>