

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2018

Submitted Date:

07/16/2018

Document Number:

677900835

FIELD INSPECTION FORM

Loc ID 303736 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa | | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 253536 | WELL | PR | 06/01/2015 | GW | 125-07413 | BROWN 1A-28 | PR |

General Comment:

[Routine Inspection](#)

Location

| | | | |
|--------------------|---------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access off of CR KK | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|--|-------|--|
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Lease sign with associated wells mounted to meter shed | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|--|
| Emergency Contact Number: | | | |
| Comment: | <input style="width: 95%;" type="text"/> | | |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 80%;" type="text"/> |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

| | |
|--------------------------|--|
| In Containment: | No |
| Comment: | <input style="width: 95%;" type="text"/> |
| <input type="checkbox"/> | Multipple Spills and Releases? |

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead, VGS and meter shed | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 253536 Type: WELL API Number: 125-07413 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Brown 1A-28, 5-28, 15-28, 16-28 & Renzelman 41-33\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: [Location and access are grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT