

Inspection Photos
Location Name: Pole Gulch Unit 2
API: 05-081-60067



Photo 1. Overview of location taken at entrance facing southeast.

Inspection Photos
Location Name: Pole Gulch Unit 2
API: 05-081-60067



Photo 2. Pit.



Photo 3. Landfarm.