

Inspection Photos
Location Name: Nichols 24-06A Pad
Location ID: 450791



Photo 1. Open hatches on frac tanks.



Photo 2. Open hatches on frac tanks.

.