

WELL SITE INSPECTION FORM



00021177

Well Name #3 DinoAPI Number 05 - 001 - 08912Operator IDG 42665Permit # 890929Location SESW 8-15 59WCounty AdamsField MoorInspector Brinkley

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) Fail(N) Date ND DG WO X PR SI TA Date of Inspection Before/During Drilling Surf. Csg. Size Setting Depth Cmt. Vol. WOC time Consistent with APD casing Program? YES NO Returns Rig BOP'S Stage Tool Depth Cmt. Vol. Date of Inspection Before/During(After) Completion 11-16-90Prod. Csg. Set? yes Completion Rig/Activity Drilling Pits: Closed Open X Wellhead Installed: X Sign: Yes No XTank ID: Yes No N/A X Skim Tank/Pit: Prod. Tanks: () N BBLsEquipment tbq valve, tbq, csghd Meter Run: Yes No XBradenhead Press: Fluid: No Yes Type Well Cat.

AL/PA/DA Inspection

Date Plugged: Date Permit Expired: Hole Plugged: Yes No Pits Backfilled: Yes No Material Buried: Yes No N/A Site Clean: Yes No Bond Release OK: Yes No Fed Hole Marker: Yes No Date of Safety/Status Inspection

Comments: Rig on site. Drill pit open. Tbg hanging in
cs. ghel with tbq valve.
Note: open tbq valve with good blow ~100psi thru 2" then closed valve.

Driller ID: # 87 Y in N & A(Need Status UPDATE)Violations: Yes No Notice Sent: Yes No Date Sent: