



**Photo 1. View of the project area from the northern corner facing center. Plugged well marker in place. Tank, berms, and unreclaimed project area remain.**



**Photo 2. View of the northeastern portion of the project area from the northern corner facing southeastward. Brown vegetation is largely annual weeds such as cheatgrass (*Bromus tectorum*) and Russian thistle (*Salsola tragus*).**



**Photo 3. View of the northwestern portion of the project area from the northern corner facing westward. Well pad berm along the northeastern edge is still in place (not shown).**