

Inspection Photos  
Location Name: MLEYNEK, JACK A 4  
Facility ID: 241176



Colorado Oil & Gas Conservation Commission  
40.10463, -105.0013, 1511.0m, 293°  
2018/07/17 14:16:57

Photo 1. Wellhead



Colorado Oil & Gas Conservation Commission  
40.11539, -105.001, 1473.0m, 255°  
2018/07/17 13:54:34

Photo 2. Tank battery

Inspection Photos  
Location Name: MLEYNEK, JACK A 4  
Facility ID: 241176



**Photo 3. Weeds around wellhead**