

Inspection Photos

Location Name: Carlson - 66N61W / 22E2NW

Location #: 327707



Photo #1

Carlson 22-1 (API 05-123-15054) wellhead.

Weeds at wellhead.



Photo #2

Carlson 22-1 (API 05-123-15054) Battery

Inspection Photos

Location Name: Carlson - 66N61W / 22E2NW

Location #: 327707



Photo #3

Carlson 22-1 (API 05-123-15054) oil tanks.

Weeds around back & front of oil tanks.



Photo #4

Carlson 22-1 (API 05-123-15054) Treater

Weeds around treater & doghouse.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Carlson - 66N61W / 22E2NW

Location #: 327707



Photo #5

Carlson 22-1 (API 05-123-15054) wellhead.

**Unused equipment at wellhead
(Pumping Unit, gas engine)**



Photo #6

Carlson 22-1 (API 05-123-15054) Gas Meter House

Mechanical Conditions: Door missing



Inspection Photos

Location Name: Carlson - 66N61W / 22E2NW

Location #: 327707



Photo #7

Carlson 22-1 (API 05-123-15054) H2O tank & earthen pit

Weeds



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources