

Inspection Photos
Location Name: NGL Major Facility / C11
Location #: 435249



Photo #1

NGL C11 (API 05-123-38533) injection wellsite.



Photo #2

NGL C11 (API 05-123-38533) injection wellhead
Tubing Pressure: 620#



Inspection Photos
Location Name: NGL Major Facility / C11
Location #: 435249



Photo #3
NGL C11 (API 05-123-38533) injection wellhead
Casing Press: 0#



Photo #4
NGL C11 (API 05-123-38533) injection wellhead
Bradenhead psi: 0#

Inspection Photos
Location Name: NGL Major Facility / C11
Location #: 435249



Photo # 5
NGL C11 (API 05-123-38533)
Injection Pump Room



Photo #6
NGL C11 (API 05-123-38533)
Injection Facility View 1

Inspection Photos
Location Name: NGL Major Facility / C11
Location #: 435249



Photo # 7
NGL C11 (API 05-123-38533)
Injection Facility View 2



Photo #8
NGL C11 (API 05-123-38533)
Tank area