

GV 81-5
Api# 05-045-06679
Inspection # 689701619



Location sign photo

GV 81-5
Api# 05-045-06679
Inspection # 689701619



Tanks

GV 81-5
Api# 05-045-06679
Inspection # 689701619



Tank volume has been repaired.