

Inspection Photos
Location Name: Shaw E Unit#1
Location ID: 320394



Tuesday, July 17, 2018 08:33:06
21251 E 152nd Ave Brighton CO 80603
United States

Photo#1 Production tank and produced water pit



Tuesday, July 17, 2018 08:32:14
21251 E 152nd Ave Brighton CO 80603
United States

Photo#2 Separator

Inspection Photos
Location Name: Shaw E Unit#1
Location ID: 320394



Tuesday, July 17, 2018 08:35:13
21251 E 152nd Ave Brighton CO 80603
United States

Photo#3 Pit with vent disconnected needs reinstalled or capped



Tuesday, July 17, 2018 08:36:35
21251 E 152nd Ave Brighton CO 80603
United States

Photo#4 Wellhead and debris/fence down



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources