

Inspection Photos

07/17/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 327399

Inspection Doc. Number: 682503609

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327399



Photo 1: Photo taken from the well location, facing north. Photo location remains predominantly bare and exposed soil, or composed of undesirable weedy plant species.



Photo 2: Photo taken from the adjacent reference area, facing west. Photo shows vegetation is predominately perennial grass species such as sand dropseed, wheatgrass, etc...



Photo 3: Photo taken from the battery location, facing west. Photo shows equipment remaining on location.