

Inspection Photos

07/17/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 327240

Inspection Doc. Number: 682503615

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327240



Photo 1: Photo taken from the western half of the battery facility, facing south. Photo shows riser remaining on location.



Photo 2: Photo taken from the northwest end of the tanks. Photo shows riser remaining.