

Inspection Photos
Location Name: SHANNON-ROBERTS #3
Facility ID: 240972



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: SHANNON-ROBERTS #3
Facility ID: 240972



Photo 3. Vent hatch open



Photo 4. Trash dumped on location

Inspection Photos
Location Name: SHANNON-ROBERTS #3
Facility ID: 240972



Photo 5. Trash near wellhead



Photo 6. Stained soil under plugged 4" valve on crude oil tank