Inspection Photos
Location Name: McCallum Unit 48
API: 05-057-06028



Click here to reset the form
State of Colorado
Oil and Gas Conservation Commission

MECHANICAL INTEGRITY TEST

OGCC Operator Number: 48260
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202
Phone: (303)825-4822
Email: sfarrenkopf@kpk.com
API Number: 05-057-06028-00
Well Name: MCCALLUM UNIT 48
Location: NESE Section: 3 Township: 8N Range: 78W Meridian: 6 PM

SHUT-IN PRODUCTION WELL
INJECTION WELL
Last MIT Date:

Test Type:
Test to Maintain SI/TA status
Verification of Repairs
5-year UIC
Annual UIC Test
Packer

Describe Repairs or Other Work Attempted:

Wellbore Data at Time of Test
Producing Formation: PRREB
Perforated Interval: 1290-1312
Open Hole Interval:
Bridge Plug or Cement Plug Depth:

Tubing Casing/Annulus Test
Tubing Size: 2 7/8
Tubing Depth:
Top Packer Depth:
Multiple Packers? Yes No

Test Date
Test Date: 7/17/18
Time of Test: 5:
Casing Pressure Start Test: 990 psi
Casing Pressure After 15 Min: 990 psi
Casing Pressure End Test: 990 psi
Tubing Pressure Start Test: 0 psi
Tubing Pressure End Test: 0 psi
Test Witnessed by State Representative? Yes No
OGCC Rep Representative (Print Name): Emily Walton

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.
Print Name: Bill Wright Lease Operator (970) 238-0319
Signature: Bill Wright Title: Date:
OGCC Approval: Title: Field Inspector Date: 7/17/18
Conditions of Approval, if any:
Inspection document # 689801385

Photo 1. Photo of MIT Form 21 as filled out and signed in the field.