

## Inspection Photos

Location Name: Riley #1 Remediation Project #9490

Related Facility ID: #444670

Inspection Date: July 10, 2018



**Photo #1 – Historical release is located on a shared location operated by TEP Rocky Mountain LLC.**



**Photo #2 – Looking into NW extent of excavation.**



## Inspection Photos

Location Name: Riley #1 Remediation Project #9490

Related Facility ID: #444670

Inspection Date: July 10, 2018



**Photo #3 – PVC risers inside of excavation related to remediation attempt under previous operator using passive SVE system.**



**Photo #4 – Stockpile of soil located at SE extent of excavation.**



## Inspection Photos

Location Name: Riley #1 Remediation Project #9490

Related Facility ID: #444670

Inspection Date: July 10, 2018



**Photo #5 – View across excavation from SE with visibly-impacted soil.**



**Photo #6 – Looking west at a monitoring well cover related to Remediation Project #9490.**

