

Inspection Photo
Jolley KP 33-21
API # 045-17922
Inspection # 689301546



Location Photo #1



Location Photo #2

Inspection Photo
Jolley KP 33-21
API # 045-17922
Inspection # 689301546



Location Photo #3, Stained ground under low stage vessel



Location Photo #4, Stained ground under low stage vessel

Inspection Photo
Jolley KP 33-21
API # 045-17922
Inspection # 689301546



**Location Photo #5, Stained ground by front of
the vessel, south side.**