

Inspection Photos  
Location Name: UPRR 43 PAN AM I 31  
Facility ID: 242098



Photo 1. Wellhead/ stuffing box leak/stained soil



Photo 2. Tank battery