

Inspection Photos

07/19/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 429227

Inspection Doc. Number: 682503638
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 429227



Photo 1: Photo taken from the southwest corner of the location, facing east. Photo shows portions of the interim area that consists of sparse vegetation and/or exposed soil, and may require additional decompaction, seeding and stabilization to pass reclamation. A follow-up inspections will be conducted in a future growing season to evaluate compliance with reclamation standards. Additionally wind erosion transporting sediment from the pad may be hindering reclamation here.



Photo 2: Photo taken from the southwest corner of the location, facing northeast. Photo shows overview of the production area.

Inspection Photos

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 429227



Photo 3: Photo taken from the southwest corner of the location, facing north.



Photo 4: Photo taken from the north end of the location, facing east. Photo shows crop establishment in the interim area.