



Photo#1:
Overview of Location from access road to West.

July 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie McClung Pad Loc# 335048



Photo#2:
Site is well contoured & Slopes are robustly re-vegetated.

July 14, 2018